

AMERICAN GENERAL TOOL GROUP

Respirator 40351 (N95)

Donning Procedures

1. Cup the respirator in your hand with the nose piece at your fingertips allowing the headbands to hang freely below your hand.
2. Position the respirator under your chin with the nose piece up.
3. Pull the top strap over your head resting it high at the top back of your head. Pull the bottom strap over your head and position it around the neck below the ears. Make sure straps are not twisted.
4. Place the fingertips of two hands at the top of the nose piece. Mould the nose piece to the shape of your nose.
5. Cover the front of the respirator with both hands, sharply exhale, if air leaks around the nose, readjust the nose clip as described in Step 4, if air leaks at the respirator edges, work the straps back along the sides of the head to eliminate leakage. Repeat the procedure until the respirator fits properly.

Note: Do not wear with beards or other facial hair that may inhibit contact between the face and the edge of the respirator.

